


I-231 / I-331 PARTS LIST

ODYSSEY



Part #	Description	Cost	Qty	Total	Part #	Description	Cost	Qty	Total
660	Female Axle	\$0.40			749B	Heel Stop - Black	\$1.50		
991	Female Axle (Brake)	\$0.40			674	Heel Stop Screw	\$0.40		
632	Male Axle Screw	\$0.40			3231	Strap/Lever - White	\$1.50		
996	Bearing Alignment Insert	\$0.40			3334	Clip - Black	\$1.00		
775	Bearing Spacer	\$0.20			2231	Liner - Men's (Specify sz)	\$10.00		
608B5	Bearing - ABEC 5	\$2.00			2331	Liner - Wmn's (Specify sz)	\$10.00		
748	Heel Stop Bracket	\$1.50			BF8024CB	Wheel - 80mm RX Formula	\$4.00		

All orders must be paid by check, Visa, or Mastercard prior to shipment

All orders are required to be faxed or mailed with signature

CA residents add 8% tax
 IL residents add 7.25% tax
 PA residents add 6% tax

Subtotal	
Tax	
Shipping and Handling	\$6.25
TOTAL	

Name: _____ Signature: _____ Phone: _____

Address: _____ City: _____ State: _____ Zip: _____

MC or Visa #: _____ Exp Date: _____

1. Check the axle screws on each wheel. The male and female should be tightened firmly prior to each use.
2. Check heel stop screw before skating. The male and female should be tightened firmly. If heel stop shows substantial wear, it should be replaced.

1. Prüfen sie die schrauben aller rollen, schraube und mutter vor gebrauch gut festdrehen.
2. Prüfen sie die schraube beim stopper bevor sie fahren. Schraube und mutter gut befestigen. Ersetzen sie den stopper, wenn er abgenutzt ist.

1. Sur chaque roue, vérifiez les vis de l'essieu. Les vis males et femelles doivent être serrées fermement avant l'utilisation des patins.
2. Vérifiez les vis du frein avant l'utilisation des patins. Les vis males et femelles doivent être serrées fermement. Si le frein arrière montre des signes apparents d'usure. Veuillez le remplacer.

1. Cheque los tornillos de cada rueda, macho y hembra de los tornillos deberan apretarse antes de cada uso.
2. Cheque todos los tornillos del freno para asegurarse que esten bien apretados. Si nota que la goma del freno esta gastada, esta debera ser reemplazada por una nueva